

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

B-155-5

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name MCA Unit
2. Name of Operator Conoco Inc.	8. Farm or Lease Name MCA Unit Bty 1
3. Address of Operator P.O. Box 460 - Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>west</u> LINE, SECTION <u>16</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Maljame G-SA
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POOH w/ Hg sub.
2. G/H w/ workstring. Wash sand off retained at 3675'. Establish pump-in rate.
3. If unable to stab in retained, attempt to pick retained, run new retained to 3650'.
4. Squeeze below retained w/ 300 sacks class "C" cement w/ 2% CaCl₂. Pull out of retained & circulate 9.5 ppq mud to surface.
5. Shoot squeeze perfs at 2100' & 925'.
6. G/H w/ retained to 2000'. Squeeze below salt zone w/ 100 sacks class "C" w/ 2% CaCl₂. POOH.
7. Rig up to wellhead & attempt to circulate thru perfs at 925' & back to surface. Cement w/ 375 sacks class "C" w/ 2% CaCl₂. SI csg valve & squeeze remaining cement above salt zone. Cut off wellhead & install P&A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DE FENNEY TITLE Administrative Supervisor DATE January 12, 1968

ORIGINAL SIGNED BY JERRY NIXON

APPROVED BY DISTRICT MANAGER TITLE DATE JAN 14 1968

CONDITIONS OF APPROVAL, IF ANY: