

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Conoco, Inc.

3. Address and Telephone No.
10 Desta Dr. Ste 100W, Midland, TX 79705

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2310' FNL & 330' FWL
Sec. 22, T-17S, R-32E

5. Lease Designation and Serial No.
LC 029509A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

MCA Unit

8. Well Name and No.
40

9. API Well No.
30-25-00635

10. Field and Pool, or Exploratory Area
Maljamar Grayburg/SA

11. County or Parish, State
Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other Casing Integrity Test	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to perform the following procedure in order to prepare this well for temporary abandonment:

1. POOH with production equipment.
2. Set a plug within 100 ft. of the top perforation.
3. Pressure test the casing to 500 psi for 30 minutes.
4. RIH with tubing and circulate packer fluid.
5. POOH with tubing and completely load hole with packer fluid.

2 Potential Reasons for later re-activation:

- (a) For future re-orientation of water flood patterns.
- (b) Evaluation of recent 3-D seis run across this unit.

14. I hereby certify that the foregoing is true and correct

Signed

Joe G. Lara

Title

Sr. Conservation Coordinator

Date

1/24/96

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) JOE G. LARA

Title

PETROLEUM ENGINEER

Date

2/20/96

Conditions of approval, if any: