

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR
Box 460, Hobbs, N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 660' FEL OF SEC. 22

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4027' DF

5. LEASE DESIGNATION AND SERIAL NO.
LC-029509(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
BAISH B

9. WELL NO.
4

10. FIELD AND POOL, OR WILDCAT
MALTI, G-5A Repress

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 22, T. 17S, R. 32E

12. COUNTY OR PARISH
Lea

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☒ **Perforate & Stimulate**

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

IT IS Proposed Perforate Additional / Pay, Acidize and Scale Inhibit to Increase Production in The Subject Well.
Clean out TO 4095' and Perf 3772'-3776' and 3812-3820' w/2 ISPF.
Set RBP AT 3870' and PKR AT 3750' and Pump 500 Gals 15% NE-HCL, 2 Drums Scale Inhibitor with Treated Fresh Water.
Move RBP TO 3750' and PKR TO 3670' and Pump 500 Gals 15% NE-HCL, 2 Drums Scale Inhibitor with Treated Fresh Water.
Pull Treating Equipment, Swab Back Load and Re-Run Production Equipment,

18. I hereby certify that the foregoing is true and correct

SIGNED

Wm. A. Butterfield

TITLE

Admin. Supv.

DATE


3-22-77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side

USGS(5) File

APPROVED

RECEIVED
JUN 21 1967
U.S. DEPARTMENT OF AGRICULTURE