

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructions
verse side)

DATE
30 re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, NM 88240</i>	9. WELL NO. <i>35</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1980' FNL & 660' FWN Unit Letter E</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamae C-5A</i>
14. PERMIT NO. <i>30-025-00650</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>23-17S-32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETION	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☒
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Scrape CSG from surface to 3100'. Set pkr at 3100'. Establish pump-in rate w/30 bbls fresh water not exceeding 1500psi. Release pkr. Set cement retainer at 3100'. Pump 200 sxs class "C" cement and flush w/18 bbls fresh water. Pull out of retainer, spot 25 sxs class "C" from 3100'-2859'. Perforate squeeze hole at 2780'. Establish pump-in rate & circ w/pkr. Set cmt retainer at 2750'. Pump 350 sxs class "C" cmt. Flush to top of retainer & spot 25 sxs class "C" cmt. Spot 9.5 lb/gal salt gel from 2509'-1800'. Spot 25 sxs plug from 3100'-1059'. WOC 12 hrs. Tag top of plug at 1059'. Perf squeeze hole at 500'. Establish pump-in rate & circulate w/pkr. Pump 100 sxs class "C" cmt & circulate. Flush & POC. Spot 25 sxs class "C" plug a surface. Install P&A marker.

18. I hereby certify that the foregoing is true and correct

19. NAME *James E. Finney* TITLE *Administrative Supervisor* DATE *6/20/87*
20. SPECIAL AGENT (or State office use)
21. APPROVAL OF APPROVAL, IF ANY: TITLE DATE *7-1-87*

*See instructions on Reverse Side

Section 102, Statute 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the BLM-Carlisle (6) Hondo (2) Citrix (1) P. L. H. (1) & A

RECEIVED

JUL 2 1987

OCD
HOBBS JAMES