

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

Type of Well:



Name of Operator

Conoco, Inc.

Address and Telephone No.

10 Desta Drive Ste. 100W, Midland, Tx. 79705-4500 (915) 686-5424

Location of Well (Footage Sec., T., R., M. or Survey Description)

1910' FSL & 590' FWL  
Sec. 23, T-1°S. R-32E

5. Lease Designation and Serial No.

LC-029400A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

MCA Unit

8. Well Name and No.

76

9. API Well No.

30-025-00659

10. Field and Pool, or Exploratory Area

Maljamar Grayburg/SA

11. County or Parish, State

Lea, N.M.

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Abandonment



Recompletion



Plugging Back



Casing Repair



Altering Casing



Other

Temporary Abandonment



Change of Plans



New Construction



Non-Routine Fracturing



Water Shut-Off



Conversion to Injection



Dispose Water

Note: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Approval is requested to extend temporary abandonment for this well for another year. A valid casing integrity test within the last 5 years should be on file.

This request for temporary abandonment extension is based on future potential for reactivation of this well. Two different scenarios that could lead to reactivation are still being studied:

1. An infill drilling program in the MCA Unit.
2. Reorientation of the current waterflood patterns.

Interpretation of 3-D seismic surveys being done across the unit is expected to resolve these two possible scenarios.

I hereby certify that the foregoing is true and correct.

Signed

Title

Ann E. Ritchie  
Regulatory Agent

Date

July 23, 1997

(This space for Federal or State office use)

(ORIG. SGD.) GARY GOURLEY

Approved by

Title

Date

Conditions of approval if any

BLM(6)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

\*See Instruction on Reverse Side