

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT TRI-DATE\*  
(Other side, etc. on re-Form approved.  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 059152 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Johns "P" DE

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Maljamar Grayburg

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 24-T17S-R32E

12. COUNTY OR PARISH 13. STATE

Lea

N. Mex.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL  
WELL☒GAS  
WELL☐

OTHER

Shut-in

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FSL &amp; 1980' FWL, Unit K.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4070' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Shut-in

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all marks and zones pertinent to this work.)\*

The electric motor on this well is in need of repairs. The well has declined in production to 2 BOPD and 85 BWPL and the cost of repairs to the electric motor would be uneconomical. This well was shut in on March 29, 1971. This well has remained shut-in the entire month of May, 1971 for reason as above.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Sr. Acctg. Clerk*

TITLE Sr. Acctg. Clerk

DATE 6-3-71.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

JUN 8 1971

OIL CONSERVATION CO. INC.  
HOBBS, N. M.