	<del>_</del>	·~	
NO. OF COPIES RECEIVED			
DISTRIBUTION	NEW MEXICO OF	L CONSERVATION COMMISSION	S C 10:
SANTA FE		ST FOR ALLOWABLE	Form C-104 Supersedes Old C-104 and o
FILE	- KEGOL		Effective 1-1-65
u.s.g.s.		AND	
<del></del>	AUTHORIZATION TO 1	RANSPORT OIL AND NATURAL	L GAS
LAND OFFICE			
IRANSPORTER OIL			
GAS			
OPERATOR			
PRORATION OFFICE			
Cperator			
Conoco Inc.			
		8240	
Reason(s) for filing (Check proper bo	or)	Other (Please explain)	
New Well	Change in Transporter of:	Change of cor	porate name from
Recompletion	Oil Dry	Gas Continental O	il Company effective
Change in Ownership	Casinghead Gas Co	ndensate Iuly 1 1070	ii company effective
		July 1, 1979.	
If change of ownership give name and address of previous owner  DESCRIPTION OF WELL AND	) LEASE		
Lease Name MCA Unit	Weil No. Pool Name, Including		10050
	193 Maljamar	G-3A State, Fed	ieral or Fee
Location	<i>,</i>		
Unit Letter J : 24	e 15 Feet From The 5	Line and 26/5 Feet Fro	om The E
Cim Ectiei	c   S   reet rioin riie	Eme and reet Fro	om The
Line of Section 25 To	ownship 17 5 Range	32E , NMPM,	Lea Coun
FSIGNATION OF TRANSPOR	RTER OF OIL AND NATURAL	GAS	
Name of Authorized Transporter of C.			proved copy of this form is to be sent)
1	or concensus.	11 0	l l
Marzio Pipeline	Company	N. treeman Ave. A	trtesia NM
Name of Authorized Transporter of C	asinghead Gas or Dry Gas	Address (Give address to which an	
•		, italiata (ista adai ada ada ada ada a	proved copy of this form is to be sent)
	Greating DL + Na 1.		
Continental Oil Co.		DP.D. Box 1206. 1	Maliamar, NM
Continental Oil Co. If well produces oil or liquids,	Unit Sec. Twp. P.ge.	P.D. Box 1306, A	Maljamar, NM
Continental Oil Co.		P.D. Box 1306, A	
Continental Oil Co. If well produces oil or liquids, give location of tanks.	Unit Sec. Twp. Rge.  A 24 175 32	P.D. Box 1306, N Is gas actually connected?  Yes	Maljamar, NM
If well produces oil or liquids, give location of tanks.  If this production is commingled w	Unit Sec. Twp. Rge.  A 24 175 32	P.D. Box 1306, A	Maljamar, NM
ontinental Oil (a. If well produces oil or liquids, give location of tanks.  If this production is commingled w	Unit Sec. Twp. Rge. $A 26 175 32$ With that from any other lease or po	P.D. Box 1306, N Is gas actually connected?  Ves ol, give commingling order number:	Maljamar, NM When
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA	Unit Sec. Twp. Rge.  A 26 175 32  With that from any other lease or po	P.D. Box 1306, N Is gas actually connected?  Ves ol, give commingling order number:	Maljamar, NM When N/A
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completion	Oil Well Gas Well ion $-(X)$ Sec. Twp. Rge. $A$ 24 175 32 with that from any other lease or po	P.D. Box 1306, N Is gas actually connected?  Ves ol, give commingling order number:	Maljamar, NM When
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA	Unit Sec. Twp. Rge.  A 26 175 32  With that from any other lease or po	P.D. Box 1306, N Is gas actually connected?  Ves ol, give commingling order number:	Maljamar, NM When N/A
if well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completion	Oil Well Gas Well ion $-(X)$ Sec. Twp. Rge. $A$ 24 175 32 with that from any other lease or po	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen	Malsamar, NM When SIA  Plug Back   Same Restv.   Diff. Re
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completion DATA  Designate Type of Completion Date Spudded	Unit Sec. Twp. Rge. $A$ 26 175 32 with that from any other lease or point on $A$ Cil Well Gas Well Date Compl. Ready to Prod.	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen  Total Depth	When Same Resty. Drift. Re Plug Back   Same Resty. Drift. Re
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well be a complete to the complete specific to the	Unit Sec. Twp. Rge. $A$ 26 175 32 with that from any other lease or point $A$ 17 $A$ 32 $A$ 32 $A$ 32 $A$ 32 $A$ 33 $A$ 34 $A$ 35 $A$ 37 $A$ 37 $A$ 38 $A$ 39 $A$ 30 $A$ 39 $A$ 30 $A$	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen	Malyamar, NM When SIA  Plug Back Same Res'v. Diff. Re
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well be a complete to the complete to the complete spudded.	Unit Sec. Twp. Rge. $A$ 26 175 32 with that from any other lease or point $A$ 17 $A$ 32 $A$ 32 $A$ 32 $A$ 32 $A$ 33 $A$ 34 $A$ 35 $A$ 37 $A$ 37 $A$ 38 $A$ 39 $A$ 30 $A$ 39 $A$ 30 $A$	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen  Total Depth	When Same Res'v. Diff. Re
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc.,	Unit Sec. Twp. Rge. $A$ 26 175 32 with that from any other lease or point $A$ 17 $A$ 32 $A$ 32 $A$ 32 $A$ 32 $A$ 33 $A$ 34 $A$ 35 $A$ 37 $A$ 37 $A$ 38 $A$ 39 $A$ 30 $A$ 39 $A$ 30 $A$	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen  Total Depth	When Same Res'v. Diff. Re
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc.,	Unit Sec. Twp. Rge. $A$ 26 175 32 with that from any other lease or point $A$ 17 $A$ 32 $A$ 32 $A$ 32 $A$ 32 $A$ 33 $A$ 34 $A$ 35 $A$ 37 $A$ 37 $A$ 38 $A$ 39 $A$ 30 $A$ 39 $A$ 30 $A$	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen  Total Depth	Maljamar, NM  N/A  Plug Back   Same Restv. Diff, Re
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc.,	Unit Sec. Twp. Rge.  A 26 175 32  With that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay	When SAMA NAM  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc.,	Unit Sec. Twp. Rge.  A 26 175 32  With that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation	P.D. Box 1206, A Is gas actually connected?  Ves ol, give commingling order number:  New Well Workover Deepen  Total Depth	Maljamar, NM  N/A  Plug Back   Same Restv. Diff, Re
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc.,	Unit Sec. Twp. Rge.  A 26 175 32  With that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay	When SAMA NAM  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay	When N/A  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Complete Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay	When N/A  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay	When N/A  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay	When N/A  Plug Back   Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay	When N/A  Plug Back   Same Restv. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed to the complete of the complete spudded.  Designate Type of Complete Spudded.  Elevations (DF, RKB, RT, GR, etc., Perforations.)	Unit Sec. Twp. Rge.  A   24   175   32  With that from any other lease or po  Ion - (X)   Gas Well  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE	Is gas actually connected?  Is gas actually connected?  Ves  Ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET	When N/A  Plug Back   Same Res'v.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations  HOLE SIZE	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  Tion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must b	Is gas actually connected?  Is gas actually connected?  Ves  Ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET	When NIA  Plug Back   Same Restr.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well complete to the complete to the complete to the complete spudded.  Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL	Unit Sec. Twp. Rge.  A 24 175 32  With that from any other lease or po  Tion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must b	Is gas actually connected?  Is gas actually connected?  VES  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)	When N/A  Plug Back Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top al
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well produced to the complete of the	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this	Is gas actually connected?  Is gas actually connected?  VES  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET	When N/A  Plug Back Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top air
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Complete Date Spudded  Elevations (DF, RKB, RT, GR, etc.,)  Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL  Date First New Cil Run To Tanks	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas	When N/A  Plug Back   Same Res'v. Diff. Re P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Complete Date Spudded  Elevations (DF, RKB, RT, GR, etc.,)  Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL  Date First New Cil Run To Tanks	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  ion - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this	Is gas actually connected?  Is gas actually connected?  VES  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)	When N/A  Plug Back   Same Res'v.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top ai
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Complete Date Spudded  Elevations (DF, RKB, RT, GR, etc.,)  Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL  Date First New Cil Run To Tanks	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas	When N/A  Plug Back   Same Resty. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all  s lift, etc.)
If well produces oil or liquids, give location of tanks.  It this production is commingled well production of tanks.  It this production is commingled well produced to the completion of the co	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas	When N/A  Plug Back   Same Res'v.   Diff. Re   P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top airs lift, etc.)
If well produces oil or liquids, give location of tanks.  If this production is commingled well production of tanks.  If this production is commingled well produced to the complete series of Complete spudded.  Designate Type of Complete Date Spudded.  Elevations (DF, RKB, RT, GR, etc., Perforations.)  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL.  Date First New Cil Run To Tanks.  Length of Test.	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this posterior to the complete of Test)  Date of Test  Tubing Pressure	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure	When N/A  Plug Back   Same Resty.   Diff. Re   P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choke Size
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completely than the completely complete	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this posterior to the complete of Test)  Date of Test  Tubing Pressure	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure	When N/A  Plug Back   Same Resty.   Diff. Re   P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choke Size
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL Date First New Cil Run To Tanks  Length of Test  Actual Prod. During Test	Unit Sec. Twp. Rge.  A 26 175 32  with that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbis.	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure  Water-Bbls.	When N/A  Plug Back   Same Res'v.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choke Size  Gas-MCF
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete spudded.  Designate Type of Complete Date Spudded.  Elevations (DF, RKB, RT, GR, etc., Perforations.  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL.  Date First New Cil Run To Tanks.  Length of Test.  Actual Prod. During Test.	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this posterior to the complete of Test)  Date of Test  Tubing Pressure	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure	When N/A  Plug Back   Same Resty.   Diff. Re   P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choke Size
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete spudded.  Designate Type of Complete Date Spudded.  Elevations (DF, RKB, RT, GR, etc., Perforations.  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL.  Date First New Cil Run To Tanks.  Length of Test.  Actual Prod. During Test.	Unit Sec. Twp. Rge.  A 26 175 32  with that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbis.	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure  Water-Bbls.	When N/A  Plug Back   Same Res'v.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all  s lift, etc.)  Choke Size  Gas-MCF
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete of the complete spudded by the complete spudde	Unit Sec. Twp. Rge.  A 26 175 32  with that from any other lease or po  ion - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbis.	Is gas actually connected?  Jes  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure  Water-Bbls.	When N/A  Plug Back   Same Res'v.   Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all  s lift, etc.)  Choke Size  Gas-MCF
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete of the complete spudded by the complete spudde	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING,  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this before this able for this content of the content of th	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Otl/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF	When N/A  Plug Back   Same Restv.   Diff. Re   P.B.T.D.    Tubing Depth    Depth Casing Shoe    SACKS CEMENT    oil and must be equal to or exceed top all stift, etc.)  Choxe Size    Gas-MCF    Gravity of Condensate
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete of the	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbls.  Length of Test  Tubing Pressure (Shut-in)	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  I New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)	When N/A  Plug Back   Same Res'v.   Diff. Re P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choke Size  Gas-MCF  Gravity of Condensate  Choke Size
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completed by the complete of the	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbls.  Length of Test  Tubing Pressure (Shut-in)	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  I New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)	When N/A  Plug Back   Same Restv.   Diff. Re   P.B.T.D.    Tubing Depth    Depth Casing Shoe    SACKS CEMENT    oil and must be equal to or exceed top all stift, etc.)  Choxe Size    Gas-MCF    Gravity of Condensate
If well produces oil or liquids, give location of tanks.  It this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL  Cate First New Cil Run To Tanks  Length of Test  Actual Prod. During Test  GAS WELL  Actual Prod. Test-MCF/D  Testing Method (pitot, back pr.)	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this  Date of Test  Tubing Pressure  Oil-Bbls.  Length of Test  Tubing Pressure (Shut-in)	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  I New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)  OIL CONSERV	When N/A  Plug Back Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top at s lift, etc.)  Choke Size  Gas-MCF  Gravity of Condensate  Choke Size
If well produces oil or liquids, give location of tanks.  It this production is commingled well production of tanks.  It this production is commingled well produced by the completion of the co	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this ab	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  New Well Workover Deepen  Total Depth  Top Oil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)  OIL CONSERV	When N/A  Plug Back Same Res'v. Diff. Re  P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top at s lift, etc.)  Choke Size  Gas-MCF  Gravity of Condensate  Choke Size
If well produces oil or liquids, give location of tanks.  If this production is commingled well production is commingled well completely than the specific production of tanks.  If this production is commingled well completely certify that the rules and the specific productions.  If this production is commingled well completely certify that the rules and the series of tanks.  If this production is commingled well completely certify that the rules and the series of tanks.  If well completely certify that the rules and the series of tanks.	Unit Sec. Twp. Rge.  A 26 175 32  with that from any other lease or policion — (X)  Date Compl. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this case of Test  Tubing Pressure  Oil-Bbls.  Length of Test  Tubing Pressure (Shut—in)  ICE  regulations of the Oil Conservation	Is gas actually connected?  Is gas actually connected?  Ves  ol, give commingling order number:  I New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas)  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)  OIL CONSERV	When N/A  Plug Back   Same Res'v.   Diff. Re P.B.T.D.  Tubing Depth  Depth Casing Shoe  SACKS CEMENT  oil and must be equal to or exceed top all s lift, etc.)  Choice Size  Gas-MCF  Gravity of Condensate  Choke Size  VATION COMMISSION
If well produces oil or liquids, give location of tanks.  If this production is commingled we COMPLETION DATA  Designate Type of Completing Date Spudded  Elevations (DF, RKB, RT, GR, etc., Perforations  HOLE SIZE  TEST DATA AND REQUEST FOIL WELL Date First New Cil Run To Tanks  Length of Test  Actual Prod. During Test  GAS WELL  Actual Prod. Test-MCF/D  Testing Method (pitot, back pr.)  CERTIFICATE OF COMPLIAN  hereby certify that the rules and commission have been complied	Unit Sec. Twp. Rge.  A 24 175 32  with that from any other lease or po  from - (X)  Date Compi. Ready to Prod.  Name of Producing Formation  TUBING, CASING, A  CASING & TUBING SIZE  FOR ALLOWABLE (Test must be able for this ab	Is gas actually connected?  Is gas actually connected?  Is gas actually connected?  Jes  ol, give commingling order number:  I New Well Workover Deepen  Total Depth  Top Cil/Gas Pay  AND CEMENTING RECORD  DEPTH SET  e after recovery of total volume of load of depth or be for full 24 hours)  Producing Method (Flow, pump, gas  Casing Pressure  Water-Bbls.  Bbls. Condensate/MMCF  Casing Pressure (Shut-in)  OIL CONSERV	When N/A  Plug Back Same Res'v. Diff, Res'v.

(Flanasure)

(Title)

(Date)

USGS (2) PARTHERS

Division Manager

NMOCD (5)

District Supervisor

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III. and VI for changes of owner, well name or number, or transporter or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.

RECEIVED

JUN 1 5 1979
OIL CONSERVATION COMM.
HODES, N. M.