

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WATER INJECTION WELL	5. LEASE DESIGNATION AND SERIAL NO. LC-030437(a)
2. NAME OF OPERATOR Continental Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 460, Hobbs N.M. 88240	7. UNIT AGREEMENT NAME MCA
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL + 660' FEL of Sec. 26	8. FARM OR LEASE NAME MCA Unit #4
14. PERMIT NO.	9. WELL NO. 141
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4008' DF	10. FIELD AND POOL, OR WILDCAT MALT G-SA Repress
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T-17S, R-32E
	12. COUNTY OR PARISH LEA
	13. STATE N.M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3-2-77 PUGH w/production equipment. Tagged Sill at 4100'  
Cleaned out to 4117'. Hit OHBP, drilled on it and pushed  
it down to 4142'.  
3-3-77 CO open hole to 4246'.  
3-7-77 Dumped 6 bbls. pea gravel. Fill to 4177'.  
3-8-77 Pea gravel to 4039. One sack 20/40 sand.  
3-11-77 Set squeeze pkr. at 3912'. Squeezed w/1000 gal. plug.  
Displaced plug to 3977'.  
3-12-77 Drilled plug out to 4084'. Cleaned out to 4142'.  
3-13-77 CO to 4246'.  
3-16-77 WIH w/cmt. Lined to bg.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

*W. A. Butterfield*

TITLE

ADMIN. SUPV.

DATE

5-26-77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

MAY 21 1977

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

\*See Instructions on Reverse Side

USRC (5) Mr. A. R. J. L.

RECEIVED

JUN 7 1977

OIL CONSERVATION COMM.  
WASHER, E. M.