

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
162 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

INJECT WELL

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 DESTA DR. SUITE 100 MIDLAND, TEXAS 79705-4500 (915) 686-5580

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FEET FSL & 660 FEET FWL

SEC. 26 T17S R32E, M

5. Lease Designation and Serial No.

LC058699

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

MCA UNIT 202

8. Well Name and No.

30 025 00707

9. API Well No.

10. Field and Pool, or Exploratory Area

MALJAMAR/GRAYBURG/S.A.

11. County or Parish, State

LEA COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☒ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- GIH- W/CIBP SET CIBP AT 3150 FEET
- CIR. HOLE W/9.5# BRINEGEL
- SPOT 25SKS CEMENT ON TOP CIBP 3150 FEET- 2900 FEET TAG
- SPOT 25SKS CEMENT 2200-1950 FEET BOTTOM OF SALT
- SPOT 25SKS CEMENT 1000FEET- 750FEET TOP OF SALT TAG
- PERFERATE 5½ CASING 300FEET SQUEEZE W/65SKS CEMENT FILL 5½ W/ CEMENT & 8 5/8 TO CASING PATCH WITH CEMENT
- INSTALL DRY HOLE MARKER CUT OFF ANCHOR & CLEAN UP LOCATION

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed Ronald L. Walker

Title CONSULTANT

Date 10-25-00

(This space for Federal or State office use)

Approved by

(ORIG. SGD) ALEXIS C. SWCBODA

Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date DEC 07 2000


BLM(6), OGD(3), SHEAR, POUCA, COST ASST. FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BWW

*See Instruction on Reverse Side

CURRENT WELLBORE 10-18-00



8 5/8" 22' w/ 25545 cmt

Bad casing at 30' ± Squeeze w/ 450 SKS cmt To Surface IN 1985

5 1/2" BOWEN casing Patch 96'

TOC BEHIND 5 1/2" casing 2400'

RBP 5 1/2" 14" 3152' OFF 13 PHR.

Liner Top 4" 3157'

PEAPS 4022'-4272'

T.D. 4285'

CONOCO INC.


MCA Unit 202[#]

SEC. 26 T-175, R32E

LEO County, NEW MEXICO

PROPOSED DUA AND ABANDONMENT

10-48-00



8 5/8" 22' w/ 25545 cmt

BAD CROW AT 30'± SQUEEZE W/450 SRS TO SURFACE

W/430 543 10 SURFACE
(YEM. 1985 AT 30' DOWN FROM SURFACE

54" BOWEN CASING Patch 76 SPURGE W/450 S4S CNT TO SURFACE

Perforate 5 1/2" at 300' 65545 cmT

Spot 25 515 Plug 1000 - 750'

Spot 255S Plug At 2200-1950'

T.O.C. BEHIND 5 1/2" CASING 2400' EST.

spot 25545 3150' - 2900'

CIBP 3112" 3150'

RBP 5 1/2" 14" 3152'

liner Top 4" 3157'

L.D. 51 1/2" 3486'

Perfs 4022'-4272'

4" T.D. 4285'

CONOCO INC.

MCA Unit 202

SEC. 26 T-17S, R 32E

LEA County NEW MEXICO

BUREAU OF LAND MANAGEMENT
Roswell Field Office
2909 West Second Street
Roswell, New Mexico 88201
505-627-0272

Permanent Abandonment of Federal Wells
Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within thirty (30) days from the approval date of this Notice of Intent to Abandon.

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 505-627-0272, Eddy County call 505-234-5972; for wells in Lea County call 505-393-3612.

3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer, such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

(rev. 5/30/2000)