

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.  
LC 0572100

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc.

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 660' FEL, SEC 27, T-17S, R-32E, UNIT LTR 'A'

8. Well Name and No. *Sty 3*

MCA UNIT #122

9. API Well No.

30-025-00716

10. Field and Pool, or Exploratory Area

MAJAMAR (G-SA)

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other CLEAN OUT

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-3-92 MIRU, POOH W/ RODS. GIH W/ 4", 4 1/4", 4 1/2" & 4 3/4" CSG SWEDGE AND SWEDGE OUT CSG @ 720' FROM SURFACE, POOH. GIH W/ 4 3/4" SWEDGE TO 2400' TO GET BELOW SALT ZONE, POOH. GIH W. BIT & SCRAPER AND TAG @ 3841'. DRILL OUT CALCIUM SULFATE SCALE TO 4110', POOH. TAG @ 4110' AND POOH W/ PUMP & TBG. GIH W/ 2 7/8" TBG AND LAND SN @ 3956', HOT OIL W/ 30 BBL OIL DOWN TBG. GIH W/ RODS & PUMP. RDMO.

RETURN WELL TO PRODUCTION ON 8-5-92

*Adz*

6 1992

14. I hereby certify that the foregoing is true and correct

Signed *John H. Keenly*

Title SR. REGULATORY SPEC

Date 9-8-92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

4000

RECEIVED  
SEP 18 1992  
OCD HOBBS OFFICE