

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bty 3</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>203</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>660' FSL & 660' FFL - Unit Letter P</u>	10. FIELD AND POOL, OR WILDCAT
14. PERMIT NO. <u>Not Available</u>	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3953' D.F. SJS</u>
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>27-17S-32E</u>	
12. COUNTY OR PARISH <u>Lea</u>	
13. STATE <u>NM</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 7/16/87. MIRR. Tag at 2555'. Circulate w/9.5 ppq mud (1954 salt gel w/75 lbs 9# brine). Shot 4' spf at 2178'. Set pk at 2140'. Establish pump in rate 2 BPM at 1300 psi. POOH. Set cement retained at 2140'. Squeeze w/75 sxs class "C" cement w/2% CaCl₂. Spot 25 sxs class "C" cement on top of retained. Tag top of cement at 861'. Perf w/4' spf at 750'. Set pk at 696'. Establish rate 3 BPM at 800 psi. POOH w/pk. Set retained at 693'. Squeeze w/25 sxs class "H" w/3% CaCl₂ on top of retained. Perf 4' spf at 250'. Squeeze w/115 sxs class "H" cement w/3% CaCl₂. Circulate cement back to surface. Displace through wellhead. Cut off csg. Install P&A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED James J. Finney

TITLE Administrative Supervisor

DATE August 20, 1987

(This space for agency or State office use)

APPROVED BY
COMMISSIONER OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

For use by the Bureau of Land Management only.
Do not use for other purposes.
Return to Bureau of Land Management, Washington, D.C.

*See instructions on Reverse Side

SEP 3 1987

SJS

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) Hondo (2) Citrus (1) Petric L. L. D.