

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
CONS. COMMISSION

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Bty 3</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>206</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>660' FSL & 660' FWL - Unit Letter M</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-SA</i>
14. PERMIT NO. <i>30-025-00729</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>27-17S-32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) <i>Clean Out & Frac</i>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work Started 7/17/87. MIRR. Jet wash 3636'-3770'. Set pks at 3555' Run base gamma ray temp log. Tag 75 bbls H PG at 18 BPM & 2000 psi. Log & maintain csq at 1000 psi. Sand frac at 25,000 #16-30 sand and 3425 gals crosslink gel. Swab well. Tag sand at 3997'. Hole caved at 3915'. Clean out 3915'-3979'. Tag at 3979. Clean out 3979'-4066'. Run producing equipment & place on production. Completed 8/13/87

ACCEPTED FOR RECORD

SJS
CARLSBAD, NEW MEXICO

RECEIVED
OCT 5 9 19 AM '87
CARLSBAD RESOURCES
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* J.F. Finney TITLE *Administrative Supervisor*

DATE *October 1, 1987*

(This space for Federal or State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) Hondo (2) Citrus (1) Pecos-Louis (1) S:0