

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Queen B
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1249' FSL & 2605' FSL - Unit Letter O	10. FIELD AND POOL, OR WILDCAT Pearson Queen
14. PERMIT NO. 30-025-00731	15. ELEVATIONS (Show whether DP, RT, GR, etc.)
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Tag fill at 3327'. Load hole w/ 80 bbls FW. Pump 11.5 sxs 20/40 sd. Tag top of sand at 3300'. G1H w/ 5 1/2" cement retained & set at 3081'. Pump 50 sxs class "C" neat cement below retained at 1 BPM & 1750 psi. Spot 25 sxs class "C" neat cement on top of retained. TOC at 2859'. Circ. hole w/ 60 bbls 10" mud. Pull up to 2278' & lay down 15 jts 2 7/8" workstring. Spot 25 sxs of class "C" neat cement from 2278'-2239'. Rev clean. POOH. G1H and perf at 1075'. POOH. G1H & set pkr at 1003'. Est circ at 2.5 BPM & 300 psi. Rel pkr & POOH. Set cement retainer at 1003'. Empd 175 sxs class "C" neat cement below retained at 2.5 BPM & 800 psi. Spot 25 sxs class "C" neat cement above retained. Pull up 243' & spot 25 sxs class "C" neat cement to surface. Install P&H marker on 5119/88A

18. Bureau certifies that the foregoing is true and correct

SIGNED DE FINNEY

TITLE Administrative Supervisor

DATE June 27, 1988

FOR STATE (or Federal or State office use)

SGD: RAJ GIRI

APPROVED BY MINERAL RESOURCES

TITLE

DATE 7-18-88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Whoever makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BK M. Carlsbad (6) File