

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other Instructions on
Reverse Side)Form approved,
Budget Bureau No. 42-R14-1-1
5. LEASE DESIGNATION (See Form 9-372)LC 057240
6. IF INDIAN, ALLOTTEE OR TRIBAL NATIVE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposed drilling or completion or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME MCA
2. NAME OF OPERATOR Continental Oil Company	8. PERM OR LEASE NAME MCA Unit
3. ADDRESS OF OPERATOR Box 460, Hobbs, N.M. 88240	9. WELL NO. 152
4. LOCATION OF WELL (On port location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1980' FNL OF Sec. 28	10. FIELD AND POOL, OR WILDCAT MCA-3, G.S. 1980' FNL
14. PERMIT NO.	11. SEC., T., R., M., OR LAND SURVEY OR AREA Sec. 28, T. 17S, R. 22E
15. ELEVATIONS (Show whether DE, RT, GR, etc.) 3981' DF	12. COUNTY OR PARISH, STATE LEA N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐

(NOTE: Report results of multiple completion on both Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Tagged TD @ 4128'. Run plug, opened to 4122' & spotted 1/2 sh. Class "C" cmt. Chased out to Toe 4092'. Plugged back w/ Hydramite to 4072'. Set open-hole bridge plug @ 3705' & spotted Hydramite on top 3705'-3694'. Set 5 1/2" pkr @ 3503'. Sq. OH w/ 2500 gals HOWCO "Injectrol" followed w/ 600 gals. HOWCO "PWC" Plug. Laid approx. 30' plug in csq. Drilled out w/ 4 3/4" bit to 3686'. Drilled & pushed OH bridge plug to 4072'. Set Baker Tension pkr. @ 3573 w/ 2 3/8" J-55 tubing. Installed injection lines & began injection. Work started 1-8-75, completed 2-6-75.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

FEB 20 1975

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

USGS-5, MCA-3, File

*See Instructions on Reverse Side