

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>151</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1980' FNL & 1980' FEL - Unit Letter G</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljama G-SA</i>
14. PERMIT NO. <i>30-025-00739</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>28-17S-32E</i>
15. ELEVATIONS (Show whether DF, ST, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) <i>Convert to Cased Hole</i>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Drill out & jet wash to 4112' (TD) Run OH calipers to 3500' (TD) Spst 36 bbls 15% HCL-NE-FE acid from 3730'-4112'. Empd 60 bbls resin pack. Empd add 25 bbls. Drill out resin pack from 3632' to TD. Underream from 3560'-3950'. Mill from 3950' to TD. Run lined to TD & set w/160 sx of 50/50 Pozmix class C cement. Drill out from 4065'-4111'. Run G-R-CBL. Perf 7th zone w/1 ispf from 3886'-3979'. Perf 9th zone w/1 ispf from 4016'-4100'. Acidize & chemical inhibitor. Perf 6th zone w/1 ispf from 3728'-3938'. Acidize & free 6th zone. Run producing equipment & place on production.

RECEIVED
JUL 21 11 51 AM '88
CARLSBAD AREA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Administrative Supervisor

DATE July 14, 1988

(This space for Federal or State office use)

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

[Signature]
JUL 27 1988

*See instructions on Reverse Side

CARLSBAD, NEW MEXICO

Section 102 of the National Archives Act, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-CA-Field (6) OYU (1) FRAC (1) L.P.