

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

PERMIT IN COMPLIANCE
WITH THE FEDERAL OIL
CONSERVATION ACT

Form approved
Budget Form No. 47-R1124
CLASSIFICATION AND SERIAL NO.
LC-057210
U. S. INDIAN, ALLEGED OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposed drilling or for open or plug back on different reservoirs.
Use APPROPRIATE FORM FOR EACH TYPE OF WELL FOR EACH PROPOSAL)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Use 47 location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FSL & 660' FEL of Sec 28

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)
3973' DF

6. UNIT AGREEMENT NAME
MCA

7. FARM OR TRACT NAME
MCA Unit 1, 2, 3

8. WELL NO.
179

10. FIELD AND POOL, OR WILDCAT
MALT. GSA Repress.

11. SECTION, TOWNSHIP, RANGE, OR BLK. AND SURVEY OR AREA
Sec. 28, T-17S, R-32E

12. CO. OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Install 4" Casing

(Note: Report results of multiple completion on Well Completion or Recomplet on Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4-27-77 Set OHBP at 3762'. Dumped 25x 10-20 frac sand.
4-30-77 with w/sand line. tagged at 3840'. Dumped 3 yards pea gravel. Tagged gravel at 3640'. Too much fill. Circulated & sand pumped excess gravel.
5-4-77 with w/airjt. 4" casing. Set at 3756'. Cmt. w/ 150sx Class C w/ 270 CaCl₂, 470 gel, 1/2" sk floccle. Tailed in w/ 100sx Class C-270 CaCl₂ & 1/4" sk floccle. Weld 4"x7" swage on casing. with w/ 3 5/16" bit. Tagged cmt. at 3640'. Drilled down to float shoe. Milled out float shoe. CO to TD 4123'.
Big up to produce.

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

MAY 27 1977

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS(5), MCA(4), File(2)