Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135 Expires: March 3 1 ,1993	FORM APPRO	VED
Expires: March 3 1 1993	Budget Bureau No.	1004-0135
	Expires: March 3	1,1993

5 Lease Designation and Serial No.

_			
1	\sim	0570	1 6
	•	117/	1.6

7. If Unit or CA, Agreement Designation

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICA TE

6. If Indian, Allottee or Tribe Name

I Type of Wall			
Oil Gas Well Other Injection Wel	1	8 Well Name and No	
2. Name of Operator		╡	
Conoco Inc		MCA Unit #209	
3. Address and Telephone No.		9. API Well No.	
10 DESTA DR. STE. 100W, MIDLAND, TX 79705-4500 (915) 686-5580		30-025-00748	
		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T. R. M. or Survey Desc	4. Location o Well (Footage, Sec., T. R. M. or Survey Description)		
		Maljamar Grayburg/SA 11. County or Parish, State	
660' FSL & 1980' FV	WL, Sec. 28, T17S, R32E, N	11. County of Farish, State	
	, , ===,,,,		
		Lea, NM	
The CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Cl. cm	
	Recompletion	Change of Plans	
Subsequent Report	, ·	New Construction	
subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	Other Permanently Abandon Zone	Dispose Water	
		Note: Report results of multiple completion on Well	

- 12/1/00 MIRU NUBOP and release off on/off tool. On/off tool would not release packer; come uphole 15', would not go back down. Casing pressured up to 600#. SD
- 12/4/00 Bleed casing down into truck. Try to release off on/off tool; could not. Packer would not release. SD. Wire line truck will pull plug out of r nipple in a.m.
- 12/5/00 RU Pro-wire line and attempt to pull plug. Could not get down to plug. Stopped 30' short. RD wire line and shear packer. PCOH w/122 jts of tubing. 1 jt of tubing and packer in hole. Loaded casing w/10# brine. Picked up 2 3/8" work string w/spear and RIH w/28 jts and shut down.
- 12/6/00 Pick work string up and latch on to fish. (Sheared packer) tubing. Lost all weight and came up hole 4'. Closed BOP. Pu nped 32 bbls down casing and 14 bbls down tubing of 10# brine. Pressured to 1000# on casing. Tried to go back down ho e; could not. Well started to flow. Opened valve to battery and flow well over night.
- 12/7/00 Well flowing up casing. RDMO

or representations as to any matter within its jurisdiction

An Intent to Plug and Abandon the remaining wellbore will be forthcoming.

14 I hereby certify that the foregoing is true and correct Signed	Reesa R. Wilkes	
	Regulatory Specialist	Date1/9/01
(This space for Federal or State office use)		
Approved by Conditions of approval if any	Title	Date
BLM(6), NMOCD(3), SHEAR, PONCA, COST ASST, (FILE ROOM, FIELD .	