

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN 1 LOCATE
(Other instructions on reverse side)

LEASE DESIGNATION AND SERIAL NO.
LC-0299410A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection	7. UNIT AGREEMENT NAME MCA Unit 6ty 2
2. NAME OF OPERATOR CONOCO INC	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	9. WELL NO. #169
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 1480' FSL & 330' FWL Unit L	10. FIELD AND POOL, OR WILDCAT Malamar (G-SA)
14. PERMIT NO. 30-025-00755	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29 T17S R32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANE	☐

(Other) Modify Injection Profile

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to modify the profile on MCA #169 by: Killing well w/weighted fluid. Shut off a thin layer in the Hayburg 6th zone w/a phenolic gel. Pump scale converter in the San Andres 7th and San Andres 9th zones. Run injection equip. Acidize. Return to water injection. Run step-rate test. Convert to CO₂ injection. See attached schematic.

18. I hereby certify that the foregoing is true and correct

SIGNED

H.A. Ingram

TITLE Conservation Coordinator

DATE

5/4/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

FOR RECORD ONLY

TITLE

DATE

MAY 16 1990


(3)OCD

*See Instructions on Reverse Side

MCA # 169

WELLBORE SKETCH

UPDATED: 6/6/88



NOTE: COULD BE OPEN HOLE BRIDGE PLUGS IN THE HOLE BELOW T.D. THERE COULD ALSO BE BRIDGE PLUG PIECES IN THE SHOT HOLE