

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

LC-029410A

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Well	7. UNIT AGREEMENT NAME MCA Unit
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME MCA Unit Bly 2
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 213
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FWL - Unit Letter N	10. FIELD AND POOL, OR WILDCAT Maljamar C-5A
14. PERMIT NO. 30-025-00757	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-17S-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☒ Convert to Cased Hole	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 2/9/88. MURU. Clean out & jet wash open hole to 4166'. Press test csq to 2000 psi, held okay. Run caliper & pmp - in traces. Spot cement plug 4169'-4010'. Tag at 4038'. Spot acid in open hole. Circulate cement. Pump 35 bbls "Ruddle Pack" resin slurry. Tag top of resin at 3741'. Drill out to 3795'. Fell out 3902'. Drill out to 4166'. Hit junk. Underream 3902'-4155'. Run liner to 4135'. Cement liner w/125 sxs 50/50 pozmix class "C" cement. Drill out cement to shoe at 4129'. Test liner to 500 psi, held okay. Run CBH. Swab down fluid level. Perf 4126'-3880' for total of 285 perms. Place well on injection.

18. I hereby certify that the foregoing is true and correct

SIGNED DE FINNEY

TITLE Administrative Supervisor

DATE May 13, 1988

(This space is for internal or State office use)

ACCEPTED FOR RECORD

APPROVAL OF
COMMISSIONER OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Blm-Carlsbad(6) Oxy(1) FPCO(1) File