(June 1990) B BUREAU OF SUNDRY NOTICES Do Bat use this form for proposals to dr	N. N. ON CONS. COMM. N P. O. BOX 1960 TED STATES HOBBS, NEW MEXICO 88240 TOF THE INTERIOR LAND MANAGEMENT AND REPORTS ON WELLS fill or to deepen or reentry to a different reservoin R PERMIT—" for such proposals	5. Lease Designation and Serial No. LC 029410A 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
 Type of Well Gas Well Gas Well Other Name of Operator Conoco Inc. Address and Telephone No. Desta Drive STE 100W, Midla Location of Well (Footage, Sec., T., R., M., or Survey D 6601 FNL & 19801 FWL, SEC. 29, 		8. Well Name and NoBi y 2 MCA UNIT, #110 9. API Well No. <u>30-025-00758</u> 10. Field and Pool, or Exploratory Area MALJAMAR (G-SA) 11. County or Parish, State
	s) TO INDICATE NATURE OF NOTICE, REP	DRT. OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	·····
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
 13. Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true vertiin the subsurface locations and measured and true vertiints. 	TBG. KILL WELL W/ 225 bbl 10# BRINE OF 3972', POOH. S & NEW PUMP. O PRODUCTION.	Dispose Water (Note: Report results of multiple completion on Wel Completion or Recompletion Report and Log torm ting any proposed work. If well is directionally drill WIH W/ BIT, COLLERS
 13. Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true vertiin the subsurface locations and measured and true vertiints. 	MX Other CLEAN OUT Il pertinent details, and give pertinent dates, including estimated date of star cal depths for all markers and zones pertinent to this work.)* TBG. KILL WELL W/ 225 bbl 10# BRINE OF 3972', POOH. S & NEW PUMP. O PRODUCTION. ' AND PUMP FROM 2 1/2 X 1 1/2 X 18'	Dispose Water (Note: Report results of multiple completion on Wells Completion or Recompletion Report and Log form is ting any proposed work. If well is directionally drille WIH W/ BIT, COLLERS