

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other. INJECTION

2. Name of Operator
Conoco Inc.

3. Address and Telephone No.
10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FNL & 1980' FWL, SEC. 29, T-17S, R-32E, UNIT LTR 'F'

5. Lease Designation and Serial No.

LC 029410A

6. If Indian, Allotment or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
MCA UNIT # 157

9. API Well No.
30-025-00760

10. Field and Pool, or Exploratory Area
MALJAMAR GRAYBURG SA

11. County or Parish, State
LEA, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-29-90 MIRU. POOH W/ TBG. GIH W/ 4 1/2" CMT RET. SET @ 3308'. PUMP 100 SX CMT, DISPLACE 75 SX UNDER RETAINER. STRING OUT OF RET. DISPLACE 25 SX ON TOP OF RETAINER. TAG TOP OF CMT @ 3000'. CIRC HOLE W/ 10# GELLED BRINE. PUH TO 1900. SPOT 80 SX CMT PLUG. TOP OF PLUG @ 920'. PERF 4 1/2" & 7" SQUEEZE W/ 100 SX CMT. FILL 4 1/2" W/ 75 SX. TAG TOP OF CMT @ 464". CIRC CMT UP 7". PUMP 19 BBL CMT. RIG UP ON 8 5/8" PUMP 5 BBL CMT. TO SURFACE. CUT OFF WELLHEAD. CLEAN LOCATION. INSTALL P&A MARKER. RDMD

Approved as to plugging of the well bore,
Liability under this well includes until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Bill A. Keady

Title

SR. REGULATORY SPEC.

Date

6-1-92

(This space for Federal or State office use)

REGIONAL ENGINEER

Approved by

med by ALAN C. ...

Title

Date

6-16-92

Conditions of approval, if any: