

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1421.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>Water injection well</i>	7. UNIT AGREEMENT NAME <i>MCA</i>
2. NAME OF OPERATOR <i>Continental Oil Company</i>	8. FARM OR LEASE NAME <i>MCA Unit</i>
3. ADDRESS OF OPERATOR <i>P. O. Box 460, Hobbs, New Mexico 88240</i>	9. WELL NO. <i>217</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>660' FSL + 1980' FWL. of Sec. 30, T-17S, R-32E, Lea County, N. Mex.</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar Pools (G-5A) Pool</i>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec. 30, T-17S, R32E</i>
15. ELEVATIONS (Show whether Dr, Rt, Cr, etc.) <i>3883 DF</i>	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>N. Mex.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☒
(Other) <i>Deepen</i>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In order to open all possible productive zones to water injection, it is proposed to deepen this well by the following procedures:

Clean out fill and drill to a new TD of 4033 (approx. 43'). Run G.R./N log from TD to 3000'. Run 2 3/8" OD cement-lined tubing with packer and set packer at 3525'. Run approx. 495' of 2" tail pipe to be set at 4020 if needed. Place well back on injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

*M. E. Gaskley*TITLE *Administrative Section Chief*DATE *1-9-69*

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JAN 13 1969

A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

V. S. G. 5

MCA Partners

266