

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1421.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>Water Injection Well</i>	7. UNIT AGREEMENT NAME <i>MCA</i>
2. NAME OF OPERATOR <i>Continental Oil Company</i>	8. FARM OR LEASE NAME <i>MCA Unit</i>
3. ADDRESS OF OPERATOR <i>P. O. Box 460, Hobbs, New Mexico 88240</i>	9. WELL NO. <i>166</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>1980' FSL & EL of Sec. 30, T-17S, R-32E, in Lea County, N. Mex.</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljuman Reservoir (H-8.03) Prod</i>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SUEVEY OR AREA <i>Sec. 30, T-17S, R-32E</i>
15. ELEVATIONS (Show whether DT, RT, CR, etc.) <i>3093' DF</i>	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>N. Mex.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) <i>Deepen</i>	<i>X</i>		

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to deepen this well by the following procedures:

Clean out fill & drill to a new TD of approx 4066' (88'). Run G.R./N log from TD to 3,000'. Run 2 3/8" cement-lined tubing with packer and set packer at 3750'. Run approx. 700' 2" tail pipe to 4050' if required. Drill 16-1/2" holes over 4' section of bottom joint of tail pipe. Plug well back on production.


18. I hereby certify that the foregoing is true and correct

SIGNED *M. E. Yeakley*TITLE *Administrative Section Chief*DATE *1-9-69*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side

V.S.S.-5

MCA Bitumex Feb.