

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
P. O. BOX 1080
HOTEL, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bty 1</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>219</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>660' FNH & 1980' FWL - Unit Letter C</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar G-5H</u>
14. PERMIT NO. <u>30-025-00785</u>	15. ELEVATIONS (Show whether DF, RT, CR, etc.) <u>31-175-32 E</u>
12. COUNTY OR PARISH <u>Lea</u> 13. STATE <u>NM</u>	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PELL OR ALTER CASING ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) <u>Re-enter & Rtn to Production</u> ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 2/15/89. MURU. Run bit, csg scraper & WS to CIBP at 3828'. Displace w/ filtered water. POOH. G1H w/ RBP & pku. Leak between CIBP at 3828' & 3745'. POOH w/ pku & RBP. G1H w/ bit, OC & WS to 3828'. DO CIBP chased to 3950'. Circ clean. Deepen to 3996'. Circ clean & POOH. Run G-R-CNL-CC Log. G1H w/ pku & WS to 3488'. Set pku & load backside to 500#. Pumped 25 bbls at 3 1/2 BPM to establish pump in rate. Pumped 100 sxs class "C" w/ 2% S-1 & 4% D-60, followed w/ 70 sxs class "C" w/ 2% S-1. Displace w/ 21 bbls wtr. Hesitate add'l 2 bbls w/ final pressure at 2000# SI. Rel & POOH w/ pku. G1H w/ bit, DC & WS to 3499'. Tag cement, DO to 4019'. Circ clean. POOH. G1H w/ scraper to 4019'. POOH. Displace w/ TFW. G1H to 3996'. Spot 1 3/4 bbl 15% HCN-NE-FC from 3996'-3924'. Displace w/ 23 bbls wtr. POOH. RU CRC. Perf w/ 1 sspF at 3967'-3990'. Perf w/ 2 sspF at 3958'-3934' & 3909'-3865'. Rig down. G1H w/ hty pku to 3838' load backside to 500 psi. Frac 6th zone w/ 1020 bbls and 72,530# sand. Release pku & POOH. Left well flwg. G1H w/ pku

18. I hereby certify that the foregoing is true and correct

SIGNED William W. Baker

TITLE Administrative Supervisor

DATE April 18, 1989

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD

DATE _____

APR 25 1989

*See Instructions on Reverse Side

SJS

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) 014(1) FPCO(1) L.L.