


SCOUT REPORT NEW MEXICO OIL CONSERVATION COMMISSION

MALJAMAR



Company Barney Cockburn

Farm Name Pearsall A

Well No. 11

Land Classification Government

Sec. 33 Twp. 17 Range 32 County Lea

Feet from Line: N. 1980 S. 1980 E. W.

Elevation

Method 5th Reg

Contractor Frank Marshall

Scout

Spudded 7-26-41 Completed 8-31-41 Initial Production

Bond Status

Amount Casing and Cementing Record

SIZE	FEET	INCHES	SAX CEMENT
<u>3 1/4</u>	<u>1144</u>		<u>52</u>
<u>5 1/2</u>	<u>1144</u>		<u>52</u>

Tubing Record

Packer

ACID RECORD

Gals.

Top Pay

TD

TA

TX

BX 2050

TRS

TY

TBL

TWL

SHOOTING RECORD

No. of Quarts 600 From 4325 To 4628

No. of Quarts From To

SINTECO-6605 SINTECO-6605-95SI

SINTECO-6605 SI SI

Success in new pay for Maljamar

DATE	3-26-41 Building Derrick	DATE	
	<u>TD 625 RB</u>		<u>1500' W & 3000' L/H</u>
	<u>1 1/2" T&B</u>	<u>7-16</u>	<u>TD 4643 L CO @ 420</u>
<u>4-9</u>	<u>TD 1154 RB 9 @</u>	<u>7-23</u>	<u>TD 4643 L CO @ 4600</u>
<u>4-16</u>	<u>TD 1552 RB</u>	<u>7-30</u>	<u>TD 4643 L plug set</u>
<u>4-23</u>	<u>TD 2805 RB</u>		<u>bridge</u>
<u>4-30</u>	<u>TD 2700 RB</u>	<u>8-6</u>	<u>TD 4643 L WOC</u>
	<u>plug & by barrel</u>		<u>on pump out</u>
<u>5-7</u>	<u>TD 2700 RB</u>	<u>8-13</u>	<u>TD 4643 L plug bridge</u>
	<u>plug @ 1460</u>		<u>@ 4340</u>
<u>5-14</u>	<u>TD 3105 RB</u>	<u>8-20</u>	<u>TD 4643 L</u>
<u>5-21</u>	<u>TD 3550 L</u>		<u>plug back 4020</u>
<u>5-28</u>	<u>TD 2805 RB</u>		<u>SDC</u>
	<u>SDC</u>	<u>8-27</u>	<u>TD 4643 L SDC</u>
<u>6-4</u>	<u>TD 4070 L</u>	<u>9-3</u>	<u>TD 4643 L</u>
<u>6-11</u>	<u>TD 4245 L</u>		<u>RB 4625</u>
<u>6-18</u>	<u>TD 4400 RB</u>		<u>plug RB 15</u>
<u>6-25</u>	<u>TD 4570 RB</u>	<u>9-10</u>	<u>TD 4643 L</u>
<u>7-1</u>	<u>TD 4643 L</u>		
	<u>SDC</u>		
<u>7-9</u>	<u>TD 4643 L CO @ 4415</u>		
	<u>13/shot well H/S/L</u>		

PVA

LOG

[illegible]