Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

N.M. Oil Cons. Division 1625 N. French Dr.

FORM APPROVED .

Budget Bureau No. 1004-0135 Hobbs, NM 88240 Expires: March 31, 1993

Lease Designation and Serial No. **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS LC-059002 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well Oil Well 8. Well Name and No. Name of Operator CONOCO Inc. MCA UNIT 229 9. API Well No. 3 Address and Telephone No. 30-025-00820 10 Desta Drive, Ste 100 W, Midland, Texas 915-686-5580 10. Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) MALJAMAR GB--SA Unit letter "E" 11. County or Parish, State 1980' FNL and 660" FWL Sed 34 **T**-17-S Lea Country New Mex CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Altering Casing Conversion to Injection Dispose Water 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) casing w brine gel 9.5 1612). spot 25 sks cmt plug class C cmt 14.8 wt 1.32 yield bottom plug 4112 and tag top of plug at 3766. 3). 10/03/00-Pooh w/ tub and Gih w/wireline and jet cutter to cut 4 1/2" casing at

3620' cut casing and try to pull casing could not. Pump fresh water down 5 1/2" casing 2 bb1 and pressure up to 1200 psi try to pump down 4 1/2" casing w/ fresh water and could not circulate. Pressured up to 1200 psi and shut down. Gih w tubing to 3670' and spot 25 sks plug bottom of plug at 3670' and tag top of plug at 3355'. 10/04/00 Pooh w/tubing and Gih w/wireline and perferated 4 1/2" casing at 2150', Pooh w/wireline and Gih packer set packer and pump into perfs at 2150',1 bb1 pm at 800 psi, Pooh w/packer and Gih w/tubing to 2200' and shut down. 10/05/00-spot 25sks plug III. an

the 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to representations as to any matter within its jurisdiction.				
(CO (3), Bum (6), SHEAR, PONCA, COST ASST	Approved as to pluge Liability under bond a	S fatained un	ell bore	
(This space for Federal or State office used IS C. SWOBODA Approved by Conditions of approval, if any:	PETROLEUM ENGINEER	Date	NOV 0 8 286	ुर] अर्थ
Signed Norall h. Mallace Tide CA	951Ng Sup.	Date	10-9-00	
. I hereby certify that the foregoing is true and correct	er)			
into perfs at 1050'-1 1/2 bpm 800 25 sks plug bottom 1100' pull abov Gih w/tub and tag top of cmt 843'		1	,	_
bottom 2200' tag top of cmt at 195 perferated at 1050' 2-shot per fee	O' Pooh w/tubing and t.Pooh w/wireline and	Gih w/	wireline ar	nd
hottom 2200! too too 5	01 5 1 / 1	, 40 DP	oc 233 mg p	٠,

Cont. from oth/side Perferated at 150', and Gih w/packer set packer and got injection rate 2 bpm 300 psi, mix cmt 30 sks displaced behind cmt inside 4 1/2" casing to perfs 2.6 bbls shut down 4 Hours, pump into perfs at 150' 1 1/2 bpm at 600 psi, mix another 30 sks cmt displaced behind cmt 2.6 bbls and shut down. 10/09/00--try to pump into perfs at 150' pressured 1000 psi could not pump into perfs at 150' released packer and Pooh w/packer and Gih w/ tubing and tag top of plug 124' Aix cmt back to surface 10 sks and install dry hole marker and cut off anchors and clean up location.