

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cities Service Oil Company	8. Farm or Lease Name H F C F
3. Address of Operator c/o Hobbs Pipe & Supply, Box 2010, Hobbs, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> , <u>440</u> FEET FROM THE <u>North</u> LINE AND <u>440</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> , TOWNSHIP <u>17-S</u> , RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat Corbin-Abo
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Propose to spot a 25 sx cement plug at 8400'.
2. Propose to spot a 25 sx cement plug at 5 1/2" casing stub at 7500'.
3. Propose to spot a 25 sx cement plug at Glorietta at 6170'.
4. Propose to spot a 25 sx cement plug at 8-5/8 casing shoe at 2750'.
5. Propose to spot a 10 sx cement plug at surface with marker.
6. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Agent</u>	DATE <u>6/3/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>JUN 4 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

*JUN - 4 1971*

**NL CONSERVATION COMM.**  
**HOBBS, N. M.**