

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01208
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-2118
7. Lease Name or Unit Agreement Name	
State G	
8. Well No.	1
9. Pool name or Wildcat	Saunders Permian Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHARLES B. GILLESPIE JR	
3. Address of Operator P.O. BOX 8 Midland, Tx. 79702	
4. Well Location Unit Letter B : 660 Feet From The north Line and 1980 Feet From The east Line Section 3 Township 15-S Range 33-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) A CIBP was set in 1991 @ 9620', cap w/35' cement
- (2) Load hole w/mud
- (3) Spot 25 sacks cement @ 6500'
- (4) Spot 30 sacks cement @ 4942', W.O.C. Tag plug @4819'
- (5) Spot 30 sacks cement @ 4296', W.O.C. Tag plug @4168'
- (6) Perforate 7 5/8 casing @ 363', squeeze 78 sacks cement, W.O.C. Tag plug @ 258'
- (7) Spot 15 sacks cement @ surface, set P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Raymond Maldonado*

TITLE *Supervisor*

DATE *11-20-93*

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY *Carly W. Hill*

TITLE

DATE

OIL & GAS INSPECTOR

JUN 15 1995

CONDITIONS OF APPROVAL, IF ANY:

*SAD*