

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01229
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-474
7. Lease Name or Unit Agreement Name	State C
8. Well No.	2
9. Pool name or Wildcat	Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Westbrook Oil Corporation
3. Address of Operator PO Box 2264 - Hobbs, NM 88241-2264	4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 4 Township 18S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-27-96 Spot 25sk plug @ 9749' No Tag
8-27-96 Spot 35sk plug @ 9749' tag @ 9626', load hole w/mud
8-27-96 Spot 30sk plug @ 6500'
8-28-96 Spot 40sk plug @ 4475' tag @ 4375'
8-28-96 Spot 40sk plug @ 3000'
8-28-96 Spot 40sk plug @ 1600'
8-28-96 Spot 60sk plug @ 700'
8-28-96 Spot 10sk plug @ surface
8-29-96 Install dry hole marker

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE V. H. Westbrook TITLE Agent DATE 9/19/96
TYPE OR PRINT NAME V. H. Westbrook TELEPHONE NO. 393-9714

(This space for State Use)

APPROVED BY

GARY W. WINK

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

JAN 23 2003