

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No. <b>B-2148</b></p>
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>W.I.W.</b></p> <p>2. Name of Operator <b>Pennzoil Company</b></p> <p>3. Address of Operator <b>P. O. Drawer 1828 - Midland, Texas 79702</b></p> <p>4. Location of Well UNIT LETTER <b>P</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>17</b> TOWNSHIP <b>17-S</b> RANGE <b>33-E</b> N.M.P.M.</p> <p>15. Elevation (Show whether DF, RT, GR, etc.) <b>4194.5' GR</b></p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name <b>Western State</b></p> <p>9. Well No. <b>10</b></p> <p>10. Field and Pool, or Wildcat <b>Maljamar Gbr. - S. A.</b></p> <p>12. County <b>Lea</b></p>

<p>6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p> <p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/> <b>Bradenhead pressure survey</b> <input checked="" type="checkbox"/></p>		<p><b>SUBSEQUENT REPORT OF:</b></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>
<p>7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</p>		

Bradenhead pressure survey witnessed by N. M. O. C. C. representative  
Mr. M. G. Crossland 2-19-79

9 5/8" x 5 1/2" Bradenhead had 0 psi

5 1/2" x 2 3/8" casing-tubing annulus - no pressure observed

BH piped to surface 0. K.

<p>8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.</p>		
<p>SIGNED <b>L. C. Marquart</b></p>	<p>TITLE <b>District Production Manager</b></p>	<p>DATE <b>3-02-79</b></p>
<p>PROVED BY <b>M. G. Crossland</b></p>	<p>TITLE <b>OIL &amp; GAS</b></p>	<p>DATE <b>MAR 7 1979</b></p>
<p>CONDITIONS OF APPROVAL, IF ANY:</p>		