

OF COPIES RECEIVED		
DISTRIBUTION		
TA FE		
E		
G.S.		
ND OFFICE		
ERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. 2149	
7. Unit Agreement Name	
8. Farm or Lease Name Phillips "B" State	
9. Well No. 2	
10. Field and Pool, or Wildcat No. 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator Pennzoil Company		
Address of Operator P. O. Drawer 1828 - Midland, Texas 79701		
Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 14-17 TOWNSHIP 17-S RANGE 33-E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

4123 K.B.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

IRM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
DRABLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
IER Set C.I. Bridge Plug <input checked="" type="checkbox"/>		OTHER <input type="checkbox"/>	

scribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed
rk) SEE RULE 1103.

8-6-74 1. Clean out to approximately 4290'.

2. Set Cast Iron Bridge Plug at 4280'.

3. Treat Grayburg perms. (4054-4260' O.A.) w/2,000 gallons acid followed by one drum of scale inhibitor.

4. Run tubing & rods & put on pump.

I certify that the information above is true and complete to the best of my knowledge and belief.

<u>J. C. Raney</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>8-7-74</u>
<u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>AUG 14 1974</u>

NS OF APPROVAL, IF ANY: