

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 2149
7. Unit Agreement Name
8. Farm or Lease Name Phillips "B" State
9. Well No. 8
10. Field and Pool, or Wildcat Andres Maljamar Grayburg-San/
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator PENNZOIL COMPANY
3. Address of Operator P. O. DRAWER 1828 - MIDLAND, TEXAS 79701
4. Location of Well UNIT LETTER 0, 2310 FEET FROM THE East LINE AND 990 FEET FROM THE South LINE, SECTION 17-17 TOWNSHIP 17-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start work approximately July 24, 1972

1. Pull rods & tubing
2. Set wire line bridge plug at 4050'. (Overall perforations 4078-4220')
3. Run tubing & displace casing w/treated salt water
4. Pull tubing & install wellhead w/pressure gauge for monitoring.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. C. Runyan</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>6-28-72</u>
APPROVED BY <u>John Runyan</u> Geologist	TITLE _____	DATE <u>JUL 3 1972</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 5 1972

OIL CONSERVATION COMM.
HOBBES, R. B.