

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT 1
P.O. Box 1980, Hobbs, NM 88240

DISTRICT 2
P.O. Drawer DD, Artesia, NM 88210

DISTRICT 3
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL AP NO.
30-025-01496
5. Indicate Type of Lease
State
6. State Oil & Gas Lease No.
B-2148

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
1. Type of Well: OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>	2. Name of Operator The Wiser Oil Company	8. Well No. 69
3. Address of Operator 207 W. McKay, Carlsbad, NM 88220 505/885-5433	9. Pool name or Wildcat Maljamar Grayburg San Andres	
4. Well Location Unit Letter <u>K</u> Section <u>20</u> Township <u>17S</u> Range <u>33E</u> NMPM <u>Lea</u> County Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>West</u> Line 10. Elevation (Show whether DF, RKB, RT, GR, etc.)		

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/> Prepare to convert to WIW

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

April 1995 Clean out and drill new formation from 4399-4535. New TD at 4535'. Test casing. Found two holes. Squeeze hole at 1370' w/200 sx cement. Squeeze hole at 558' w/150 sx cement. Test casing to 500#, held good.

May 1995 Acidize perms 4181-4193 & OH 4234-4535 w/3000 gal 15% NEFE acid. Ran 138 jts 2 3/8" tubing and set at 4278'. Put back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jawna Harris TITLE Agent DATE 07/18/95
TYPE OR PRINT NAME Jawna Harris 505/885-5433 TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL [Signature] [Signature] TITLE SEXTON DATE AUG 09 1995
CONDITIONS OF APPROVAL IF ANY:

RECEIVED

AUG 6 1 1965
1700 HESS.
OFFICE