

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Oil of California	8. Form or Lease Name Hume Queen Unit
3. Address of Operator c/o Hobbs Pipe & Supply Company	9. Well No. #1
4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>16-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat Hume Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4150' SCF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Propose to spot a 25 sx. cement plug from 3924'-3944'.
2. Propose to spot a 25 sx. cement plug at 5 1/2" casing stub at 1400'.
3. Propose to spot a 25 sx. cement plug at 8 5/8" casing shoe at 352'.
4. Propose to spot a 10 sx. cement plug at surface with marker.
5. Hole will be loaded with mud laden fluids.

(Prod. well)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Helmer TITLE Agent DATE 10-5-70

APPROVED BY John W. Runyon TITLE DATE 10-13-70

CONDITIONS OF APPROVAL, IF ANY: