

NO. OF COPIES RECEIVED		
DISTRIBUTION		
DATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1186

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-Entry	7. Unit Agreement Name
2. Name of Operator C. W. Trainer	8. Farm or Lease Name Phillips State
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 16 S RANGE 34 E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4139 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Subsequent report of re-entry <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work began 11/11/74. Drilled out surface plug and plugs at 300' and 400'. Spliced 5 1/2" casing @ 408'. Found 5 1/2" casing parted at 420' and 464'. Found iron bridge at 1000'. Will pull 5 1/2" casing from 408' and re plug by spotting 25 sack plug at 5 1/2" casing stub, 25 sack plug at 8 5/8" casing shoe at 264' and 10 sacks at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Herminia Hall</i></u>	TITLE Agent	DATE 11/26/74
APPROVED BY <u><i>Oil</i></u>	TITLE <u><i>Oil</i></u>	DATE <u><i>NOV</i></u>

CONDITIONS OF APPROVAL, IF ANY:

ALL PLUGS to be 100' IN LENGTH MIN Required (NOTIFY COMMISSION 24 hr prior to setting btm. plug)