Submit 3 Copies District Office	State of New Me Energy, Minerals and Natural Re		Form C-103 Revised 1-1-89
2151RICT 1 20. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.
	P.O. Bux 208		30-025-01909
DISTRICT II 20. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE	TICES AND REPORTS ON WEL ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PEF C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
Type of Well: OL GAS WELL WELL X	] onex		York ARQ
Name of Operator		<u></u>	8. Well No.
YATES PETROLEUM CORPO	RATION		1
Address of Operator 105 South 4th St., Ar	tecto NM 88210		9. Pool name or Wildcat Kemnitz Morrow
Well Location	COTA, MI 00410		I Kemiticz Horrow
	0 Feet From The South	Line and19	80 Feet From The East Line
Section 12	Township 16S Ra	nge 34E	NMPM Lea County
777777777777777777777777777777777777777	10. Elevation (Show whether	DF, RKB, RF, GR, etc.)	
		68' GR	X////////////////////////////////
ı. Check	Appropriate Box to Indicate N	Nature of Notice, R	eport, or Other Data
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:
	ITENTION TO:	SUE REMEDIAL WORK	SEQUEN'T REPORT OF:
NOTICE OF IN ERFORM REMEDIAL WORK		REMEDIAL WORK	G OPNS.
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER:Perfora	ALTERING CASING
ERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS Change PLANS Charly state all pertinent details, and mast unit and wireline to logging tools and rigge on completion unit. Ind rigged up pulling unit, drill collars and 2-' wireline measurement). It collars and performer to the state of the performance of the text of text o	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CA OTHER: Perfora of give periment dates, inclu- cruck. TIH with ruck. TIH with and reverse -7/8" tubing. Rigged up sw vivel. Pickled ed 75 stands tu line. TIH with reline. nded to 13225'.	ALTERING CASING
ERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CA OTHER: Perfora of give periment dates, inclu- cruck. TIH with ruck. TIH with and reverse -7/8" tubing. Rigged up sw vivel. Pickled ed 75 stands tu line. TIH with reline. nded to 13225'.	ALTERING CASING ALTERING CASING BOPNS. PLUG AND ABANDONMENT EMENT JOB te & acidize X Adding estimated date of starting any proposed th logging tools and ran GR/CBL/ e. equipment. Tagged cement at 13174' (tubing ivel and drilled 65' of cement tubing at 13225' with 500 gallons bing. Shut down for night. logging tools and ran RST log. Displaced 10# brine from hole d hole. Tested BOP and lubricator 1-13115' with 144 .42" holes as CONTINUED ON NEXT PAGE:

: