

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

July 26, 1956

C  
Cities Service Oil Co.  
Box 97  
Hobbs, New Mex.

O  
Gentlemen:

P  
Mr. M. L. Armstrong, Oil & Gas Inspector, has inspected the locations for your State AV in Unit D of Section 13-T16S-R34E, and York in Unit N of Section 12-T16S-R34E and finds that the markers do not have the locations on them, the dead men wires are not cut and the markers need to be tightened. He also found junk pipe on the location for the York.

Y  
Please notify us when these things have been done so that he may make another inspection of the locations and approval may be made of your Report of Final Plugging without further delay.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery  
Proration Manager

mc

DIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

CCB 1, 30 JUL

•60 DIL solved certain  
•IS 100  
•XAM well, add on  
•memelthel

•sequani and subsequent add a 110, "Memelthel" .D. I. 100  
•EACR-SDIT-11 no longer to be used for amelioration add  
•add only add that EACR-SDIT-11 no longer to be used in KIRY 100  
•series new breed add , add no amelioration add evsd too o0 streak  
•cals still .benefit add of been streaked add has not yet been  
•.add add to the following add no eqip min bnum? 10000

•add os above need evsd against excess heat on which base  
•isvorqgs has amelioration add to no longer restrictions exist when add  
•add only add that EACR-SDIT-11 no longer to be used to add add  
•.ysiesb

•xam very criti

•DIL CONSERVATION COMMISSION

•ytemolog. V.  
•telenet. 10000

•500