

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 1281	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Elk Oil Company		8. Farm or Lease Name S.B.
3. Address of Operator Box 310, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER N, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 16S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Kemnitz Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was purchased from Ohio Cities Service with the hole in the following condition; 5½" casing to TD of 10,818', cement behind pipe to 8417' by log, Cement plug in pipe at 10,670, casing perforations at 8802-8819.

Elk Oil desires to plug the well by spotting 20 sx across perfs. 8800-8900'
Pull 5½" casing from 8000'
Place 20 sx plug at 8000'
Place 20 sx plug at 4800', Base 9-5/8"
Leave 9-5/8" & 13-3/8" casing in the hole
Heavy mud between all the plugs
Place 10 sx plug at surface with regulation marker
Clean up location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____	TITLE <u>President</u>	DATE <u>7/18/72</u>
Orig. Signed by Joe D. Ramey Dist. I, Supv.		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 10 1972

OIL CONSERVATION COMM.
HOODS, R. L.