State of New Mexico

linerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

30 025 01915

WELL API NO.

COLIG		
2040	Pacheco	St.

Energ

Santa Fe, NM 87505

DISTRICT II		Santa Fe, NM	м 87505	5. Indicate Type of Lease		
P.O. Drawer DD, Artesia, NM 88210				STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM	87410	6. State Oil & Gas Lease No. E-944				
		DEPORTS ON WE	11.0			
SUNDR' (DO NOT USE THIS FORM F	Y NOTICES AND	REPORTS ON WE	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
DIFFEREN	T RESERVOIR. USE	/. Lease Name of Omit Agreement Name				
(1	FORM C-101) FOR SU	Kemnitz Wolfcamp Unit				
	AS TELL	OTHER SWD		·		
2. Name of Operator		8. Well No.				
F&M Oil and Gas	Company			#8		
3. Address of Operator				9. Pool name or Wildcat		
P. O. Box 891, M	idland, Texas 7	9702		Kemnitz; Lower Wolfcamp		
4. Well Location			0.00	n m m Tool		
Unit Letter P	:660 Feet From	m The <u>South</u>	Line and66U	Feet From The <u>East</u> Line		
		400	0.417	NMPM LEA County		
Section 19	Townshi	p 16S)	Range 34E r DF, RKB, RT, GR, etc.)	NMPM LEA County		
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	///////////////////////////////////////	4136 GR	, 21, 1412, 141, 511, 511,	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
	71 -1- 1- 1		Nature of Notice R	eport or Other Data		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
NOTICE (OF INTENTION	110:	508	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG	AND ABANDON	REMEDIAL WORK	X ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT						
PULL OR ALTER CASING			CASING TEST AND CI	EMENT JOB		
OTHER:			OTHER:			
	_			The second secon		
 Describe Proposed or Complework) SEE RULE 1103. 	eted Operations (Clearly	state all pertinent details,	and give pertinent dates, inclu	iding estimated date of starting any proposed		
7-29-96 MI RUF release packer - SD SIFN	PU unflange W. start TOH. Ha	H RU on tubin id drag on tool f	g – pick packer up o or 3 stands. TOH w	off compression – had drag – / packer & tubing. LD packer		
Set packer @ 10 mixed packer flu	,601.24' W/ 20 p uid down B.S. –	points compressi Press. to 500#.	on. RU KT on casi Held OK. RDPU.			
8-09-96 RU Hot Oiler on casing valve - Met OCD Represenative on loc. (Buddy Hill) - Pressure BS to 500#- Ran chart - Held Good - RDHO- Leave Loc.						
I hereby certify that the information	above is true and complete	to the best of my knowledge	and belief.			
Lane	lall Ics		mu <u>Vice Presiden</u>	nt DATE 09-04-96		
arous arms	<u> </u>					

915 TELEPHONE NO. 682-7714 Randall Foster TYPE OR PRINT NAME ORIGINAL-SIGNES BY JERRY SEXTON DISTRICT I SUPERVISOR (This space for State Use) - TITLE -APPROVED BY ---

CONDITIONS OF APPROVAL, IF ANY: