## Submit 3 Copies to Appropriate District Office

State of New Mexico Ener- Minerals and Natural Resources Department

Form C-103

WELL API NO.

DISTRICT I	
P.O. Box 1980, Hobbs, NM	88240

## OIL CONSERVATION DIVISION P.O. Box 2088

Revised 1-1-89

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico	30-025-01933	
	5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE TEE _	
	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WE	E9538	
TO THE TOTAL PROPOSALS TO DRILL OR TO DEEDE	N OD BLUG BARKER	
I SE APPLICATION FOR PR	ERMIT 7. Lease Name or Unit Agreement Name	
(FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:		
OIL GUS C	Kemnitz Wolfcamp Unit	
2. Name of Operator		
Fina Oil and Chemical Company	8. Well No.	
3. Address of Operator	26	
P.O. Box 10887 Midland, Texas 79702	9. Pool name or Wildort	
4. Well Location	Kemnitz Lower WOlfcamp	
Unit Letter E : 660 Feet From The West	. 1980	
	Line and 1980 Feet From The North Line	
Section 28 Township 16 S R	2nge 0/ H NR CM /	
10. Elevation (Show whether	DF, RKB, RT, GR, etc.)  County  VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
4111' 6		
11. Check Appropriate Box to Indicate 1	Nature of Notice Report or Other Date	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF		
DEDECOM DELICENCE	SUBSEQUENT REPORT OF:	
	REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE	
PULL OR ALTER CASING	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
<u> </u>	CASING TEST AND CEMENT JOB	
OTHER:	OTHER:	
12. Describe Proceed or Completed O		
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, an work) SEE RULE 1103.</li> </ol>	d give pertinent dates, including estimated date of starting any proposed	
	, a >>	
, it was at it it it is all the same and it is an in the same and it is a		
2) Spot 10 sx at 7,715'-7,615' and tag  3) Cut csg at 4600' and pull  9860' by town assured tap with 3 sx.  Data: 5 1/2" csg set at 10,947' cement top at		
4) Spot 30 or at (COOL (Soot		
4) Spot 30 sx at 4600'-4500' and tag 5) Perf at 1700' and squeeze 100 sx	8 5/8" csg set at 4550' cement top at	
from 1700'-1600' and tag (top of salt)	2710' by temp survey	
b) Perf at 400' and squeeze 100 sx  13 3/8" csg set at 351' circo		
from 400'-300' and tag	perfs: 10,764'-10,780'	
7) 10 sx top plug	10,797'-10,800'	
r raag	10,823-10,832'	
100 mg (100 mg	top of salt at 1650'	
10 D1 40 D1 40 D1		
I hereby certify that the information above is true and complete to the best of my knowledge and be	did.	
SIGNATURE TO The House	Draf 11:	
LUUIS Torranc	Drilling Manger 1-11-94	
TYPE OR PRINT NAME	915	

AJTROVED BY ...

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

mme.

TELEPHONE NO. 688-0600