

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name Kennitz Wolfcamp Unit
2. Name of Operator Tenneco Oil Company		8. Farm or Lease Name Kennitz Wolfcamp
3. Address of Operator 7990 IH 10 West, San Antonio, TX 78230		9. Well No. 14
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 16S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Kennitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Clean out well to PBTD. Set RBP at 10,685'. Perforate 10,614' to 10,678' with a 4" casing gun loaded with 2 JSPF. Acidize 10,614' to 10,678'. Swab back load. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert A. Mattar TITLE Production Engineering Supv. DATE August 8, 1984

ORIGINAL NOTED BY JERRY SEXTON

APPROVED BY DAVID L. SEXTON

TITLE

DATE

AUG 14 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 13 1984

C.C.D.
HONORARY OFFICE