

OIL CONSERVATION DIVISION
 P. O. BOX 2088
 SANTA FE, NEW MEXICO 87501

Form C-103
 Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Kemnitz Wolfcamp Unit
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name Kemnitz Wolfcamp
3. Address of Operator 7990 IH 10 West, San Antonio, TX 78230	9. Well No. 25
4. Location of Well UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Kemnitz Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out well to PBTD. Perforate potential productive zones between 10,690' to 10,793' with a 4" casing gun loaded with 2 JSPF. Perforate in acid. Acidize entire perforation zone. Swab back load. Return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert A. Mattar TITLE Production Engineering Supv. DATE 30 May 1984

ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 4 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 4 1984
O.C.C.
HOBBS OFFICE