

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Morris R. Antweil	8. Farm or Lease Name F. J. Danglade
3. Address of Operator Box 2010, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER N 660' FEET FROM THE South LINE AND 1980' FEET FROM THE West LINE, SECTION 31 TOWNSHIP 15 RANGE 35 NMPM.	10. Field and Pool, or Wildcat Townsend Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4027' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows:

spot 25 sx cement plug across perfs 10,250'--10,684
cut and pull an estimated 6800' 5-1/2" casing.
spot 25 sx. cement plug across 5-1/2" casing stub @ 6800'.
spot 25 sx. cement plug at top of Glorieta (6150')
spot 25 sx. cement plug across 8-5/8" casing shoe @ 4815'.
If any 8-5/8" casing is recovered, 25 sx. plugs will be
spotted across 8-5/8" casing stub & 13-3/8" casing shoe.
10 sx. cement surface plug w/marker.
hole will be loaded with mud-laden fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R M Williams</u>	TITLE <u>Agent</u>	DATE <u>1-17-69</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		