

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.  
85190

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Lease Name or Unit Agreement Name

W. M. Snyder

2. Name of Operator  
Marks & Garner

8. Well No.  
#1

3. Address of Operator  
P O Box 70, Lovington, NM 88260

9. Pool name or Wildcat  
Townsend-Permo, Penn  
Claret

4. Well Location  
Unit Letter G : 1980 Feet From The N Line and 1980 Feet From The E Line  
Section 35 Township 15 Range 35 NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull Production Equipment
- 2) Run in hole set CIBP above perms. 10,200' cap with 35 ft. cement
- 3) Load hole with 10 lbs. salt gel
- 4) Cut & Pull 5½" casing 9000 ft +
- 5) Spot 25 sx plug at stub of casing woc & tag 50/50 in & out
- 6) Spot 100 ft plug at Glorietta 6300'
- 7) Spot 100 ft plug 50/50 of 8 5/8 shoe at 4750 & tag
- 8) Spot 100 ft plug top salt - 1900'
- 9) Spot 10 sx surface plug
- 10) Install dry hole marker & clean location

13 3/8 - 390' - C  
8 5/8 - 4750 - 2100 sx  
5½ - 10765 - 300 sx

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra M. Necaie TITLE Bookkeeper

DATE 12/26/89

TYPE OR PRINT NAME Debra M. Necaie

TELEPHONE NO. 396-5326

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON  
CONDITIONS OF APPROVAL, IF ANY: DISTRICT SUPERVISOR

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED.

DEC 26 1989