

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Er , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02704
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9117
7. Lease Name or Unit Agreement Name STATE "C"
8. Well No. 1
9. Pool name or Wildcat TOWNESEND - PERMO UPPER PENN
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3972 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
CHARLES B. GILLESPIE, JR.

3. Address of Operator
P.O. Box 8 MIDLAND TEXAS 79702

4. Well Location
Unit Letter R : 2140 Feet From The EAST Line and 2310 Feet From The SOUTH Line
Section 1 Township 16-S Range 35-E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) SET 5-1/2" CIBP AT 10,020. CAP w/35' cmt.
- 2) SPOT 25 SX cmt PLUG AT 6400'.
- 3) SET 5-1/2" CIBP AT 5775'. CAP w/35' cmt.
- 4) SPOT 25 SX cmt PLUG AT 4495'. WOC. TAG AT 4305'.
- 5) SPOT 100' cmt PLUG AT 465'.
- 6) SPOT 15 SX cmt PLUG AT SURFACE. SET P.A. MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin Widner TITLE PRODUCTION MANAGER DATE 1-3-95
TYPE OR PRINT NAME KEVIN WIDNER TELEPHONE NO. (915) 683-1765

(This space for State Use)

APPROVED BY Larry W. Sid OIL & GAS INSPECTOR JUN 15 1995
TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

42-1-1-1

42-1-1-1

RECEIVED

JAN 05 1995

OCD HOBBS
OFFICE