

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02713	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-9050	
7. Lease Name or Unit Agreement Name State "D"	
8. Well No. #4	
9. Pool name or Wildcat Townsend Permo Upper Penn	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P.O. Box 8 Midland, Texas 79702	4. Well Location Unit Letter V : 990 Feet From The South Line and 1650' Feet From The West Line Section 1 Township 16-S Range 35-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In 1964 TBG was shot off @ 9562'. Pulled TBG to 5966'. TAC became stuck. Temporarily abandoned well.

In 1968 an attempt to fish TBG was unsuccessful. TBG was shot off @ 5955'. Temporarily abandoned well.

1. Rih and attempt to fish TBG @ 5955'. If TBG cannot be fished, contact state for further guidance.
2. If TBG can be fished, set Cibp @ 9500'. Cap w/cement.
3. Spot 100' plug @ 6500'.
4. Spot 100' plug @ 8-5/8" casing shoe @ 4645'.
5. Spot 100' plug @ 5-1/2" liner top @ 4515'.
6. Spot 100' plug @ 13-3/8" shoe @ 294'.
7. Put 15 SX plug at surface.
8. Weld on 4" dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin Widner TITLE Production Manager DATE 09/15/93
(915)
TYPE OR PRINT NAME Kevin Widner TELEPHONE NO. 683-1765

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE SEP 17 1993

CONDITIONS OF APPROVAL, IF ANY: THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103