


WILD CAT



Company J. W. Brown

Farm Name _____ State _____

Well No. 1

Land Classification State

Sec. 4 Twp. 16 Range 35 County Lea

Feet from Line: N. 4620 S. E. 1980 W.

Elevation	Method
-----------	--------

Contractor	Scout
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

Spudded Completed Initial Production

Bond Status

5300' contract depth or production

TA 1735

TX

BX

TRS 7500

TY 200-687-2

TBL

TWL

ACID RECORD

Gals.

Top Pay

TD

SHOOTING RECORD

No. of Quarts	From	To
---------------	------	----

No. of Quarts	From	To
---------------	------	----

S/

S/

Amount
Casing and Cementing Record

[illegible]

Tubing Record

Packer

[illegible]

LOG

Depth	Formation	Depth	Formation	Depth	Formation
9-17	TD 5507 L				
	PH 5 1/2				
	cut R/acid				
	Sp. 1/2				
10-0	TD 5507 L				
	PH 5 1/2				
	cut R/acid				
10-1	TD 5507 L				
	PH 5 1/2				
10-8	TD 5507 L				
	PH 5 1/2				
	cut R/acid				