

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-02739 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. B-10629 |
| 7. Lease Name or Unit Agreement Name New Mexico "F" State |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Townsend Permo Upper Penn |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4040' GR |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| |
|--|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator Bison Petroleum Corporation |
| 3. Address of Operator 5809 S. Western Ste. 200, Amarillo, Texas 79110-3607 |
| 4. Well Location Unit Letter L : 660 Feet From The West Line and 3524 Feet From The North Line Section 4 Township 16S Range 35E NMMPM Lea County |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| PLUG AND ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods and tbg.
Set RBP @ 10,300'
Pump 125 Bbl wtr. down csg.
Perf. 10198-200' and 10,206-210' w/2 SPF
Acidize w/1500 gal HCl acid
Pull RBP and put on pump

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce O. Barthel TITLE President DATE 11-15-93
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 19 1993
CONDITIONS OF APPROVAL, IF ANY: