
	<u> </u>				Form C	2-103
NO. OF COPIE	S RECEIVED				Supers	edes Old
DISTRIB	JUTION			TON COMMISSION		and C+103 Ive 1+1+65
SANTA FE		NE	W MEXICO UIL CONSE	ERVATION COMMISSION	Effect	,
FILE					5a. Indica	te Type of Lease
U.S.G.S.					State	Fee X
LAND OFFI	CE				5, State C	iii & Gas Lease No.
OPERATOR		iI				
				WELLS		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)						
	USE "APPL	LICATION FOR PERMIT	Les (PORM COTOT) FOR DOCT		7, Unit A	greement Name
1. 01L	GAS WELL	OTHER-				
WELL L 2. Name of Op-						r Lease Name
	troleum				Dangl	ade Gas Com
Address of					9, Well N	°, 1
1212 V:	aughn Buildir	ng				·
4. Location of				1 000		and Pool, or Wildcat
· Location of	J	1,980	East	1,980	Town	send (Atoka-Morr
UNIT LETT		FEET	FROM THE			MMMMMM
	C	15		SRANGE35-E	NMPM.	
тне	SOUTA LINE, S					MMMMM
\overline{m}	mmm.	15.	Elevation (Show whether	DF, RT, GR, etc.)	12. Coun	*
			3, <u>987 GL</u>		Lea	
16.	Che	ck Appropriate	Box To Indicate N	ature of Notice, Repor	t or Other Data	
		OF INTENTION T		SUBSE	EQUENT REPOR	T OF:
	NOTICE O		-		<u></u>	r
PERFORM REM			PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
				COMMENCE DRILLING OPNS.		PLUS AND ASANDONMENT
TEMPORARILY			CHANGE PLANS	CASING TEST AND CEMENT JOB		r
				OTHER		k
OTHER				4.1		2 - A
		(0)	1	ails, and give pertinent dates,	including estimated	date of starting any propos
		م مراجع المراجع ال	. Doplacad al	d 2-3/8" OD 4.70# 3]-55 tubing v	with good
1. Pull	led old packe	er and tubing	J. Replaced Un			Ŭ
reco	onditioned 2-	-3/8" 00 4.70	J# N-80.			
				trawn). First stag 5 sx Class C. Sque	ae 100 sx C1	ass "C", did not
2. Sque	eezed old per	rforations @	10,954-960 (3)	5 sx Class C. Sque	eezed to 500	0 psi and revers
sque	eeze. Second	d stage 50 sx	Class n and 7.			
out	55 sx.					
		c . 10 00/1	+0 10 800' and	cleaned hole out min. Had 15 psi d	to 11,472' (PBTD) and tested
3. Dri	lled cement	trom 10,884	10 nci for 30	min. Had 15 psi d	rop in press	ure.
6.011	eeze job and	casing to su	100 psi 101 00 i			
syu			h clean 44° API	oil. Perforated	7" casing th	rough tubing
	• • • • • • •	the help with		AND	th 4 swing j	et charges/ft.
	placed water	in hole with	1 330') from]]	417 to 11,435° WI	•••••••••	
4. Dis (Ba	ker Model Pa	cker set e i	1,000 / 1101111	,		
4. Dis (Ba	ker Model Pa	cker set e i	1,000 / 1101111	,		
4. Dis (Ba	ker Model Pa	and flowed	tubing load and	gas into test tan	k, flowed we	ell to clean up.
4. Dis (Ba	ker Model Pa	and flowed	tubing load and	gas into test tan	k, flowed we	ell to clean up.
 4. Dis (Ba 5. Wel 6. Ran 	ker Model Pa 1 kicked off Potential t	and flowed	tubing load and	,	k, flowed we	ell to clean up.
 4. Dis (Ba 5. Wel 6. Ran 	ker Model Pa	and flowed	tubing load and	gas into test tan	k, flowed we	ell to clean up.
 4. Dis (Ba 5. Wel 6. Ran con 	ker Model Par 1 kicked off Potential t densate/MMCF	and flowed est. Calcul	tubing load and ated absolute o	gas into test tan open flow for 15,20	k, flowed we	ell to clean up.
 4. Dis (Ba 5. Wel 6. Ran con 	ker Model Par 1 kicked off Potential t densate/MMCF	and flowed est. Calcul	tubing load and ated absolute o	gas into test tan open flow for 15,20	k, flowed we	ell to clean up.
 Dis (Ba Wel Ran con 	ker Model Par 1 kicked off Potential t densate/MMCF	and flowed est. Calcul	tubing load and ated absolute O	gas into test tan	k, flowed we	ell to clean up.

APPROVED			
CONDITI	ONS OF	APPROVAL.	IF ANYI

TITLE _

DATE _

REDUINED

OIL CONSERVATION COMM. DOBLE N. M.