

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

APR 11 35 AM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sinclair Oil & Gas Company	8. Farm or Lease Name Eidson A WN
3. Address of Operator Box 1920, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Shoe Bar Devonian
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12,668' TD 13-3/8" csg set @ 345' & cement circulated to surface.  
9-5/8" csg set @ 4888' & cement circulated to 450' fr surface.  
5-1/2" csg set @ 12456' & cemented back to 10230' fr surface.

### PROPOSE TO PLUG AND ABANDON AS FOLLOWS: (With hole full heavy mud between plugs)

Set 25 sk cement plug at base of 5-1/2" csg at 12456'.  
Cut & pull 5-1/2" csg fr appr. 10200'.  
Set 25 sk cement plug in top of 5-1/2" csg stub.  
Set 25 sk cement plug across top of Penn. Zone (top of Penn: 10248')  
Set 25 sk cement plug across top of Wolfcamp Zone (top of Wolfcamp: 9410')  
Set 25 sk cement plug across top of Abo Zone (top of Abo: 8207')  
Set 25 sk cement plug across top of Glorieta Zone (top of Glorieta: 6222')  
Set 10 sk cement at surface.  
Set Regulation marker & clean & level location.

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frederick TITLE Supt. DATE 3-30-67

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

